PATENT

03500.017659

6	PE	IAPI	\   
, \	SEP 1	8 2005	*OFFICE
199	ENT &	TRADE	n re P

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

n re Patent of:	)	
JUNICHI SEKIYAMA ET AL.	:	Examiner: Henry H. Nguyen
JONION SERTAMA ET AL.	;	Group Art Unit: 2851
Appl. No.: 10/684,468		
77.10	:	Confirmation No.: 4699
Filed: October 15, 2003	)	
For: SHEET POST-PROCESSING DEVICE A	: ND)	
IMAGE FORMING APPARATUS HAVING	:	Certificate
THE DEVICE	)	
IIG D N COLO OLL DO	:	SEP 2 2 2005
U.S. Patent No.: 6,912,044 B2	)	of Correction
I1. I 20 2005	:	
Issued: June 28, 2005	)	September 16, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# **CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,912,044 B2

DATED

June 28, 2005

INVENTOR(S) :

JUNICHI SEKIYAMA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 1:

Line 55, "let" should read --lets--.

### COLUMN 3:

Line 64, position" should read --positions--.

### **COLUMN 8**:

Line 9, "10A." should read -- 100A.--.

### COLUMN 10:

Line 35, "angle a." should read --angle  $\alpha$ .--

#### COLUMN 11:

Line 23, "slid" should read --slide--.

Line 66, "guides" should read --guides to--.

#### COLUMN 13:

Line 64, "a side" should read --a part of the slide guide 302 that is on the upstream side--.

#### COLUMN 14:

Line 43, "301 and" should read --301 and 302--.

### COLUMN 15:

Line 21, "rotated" should read --rotated in--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 6,912,044 B2

No. of add'l. copies @ 30¢ per page

# **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,912,044 B2

DATED

June 28, 2005

INVENTOR(S) :

JUNICHI SEKIYAMA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 20:

Line 25, 'punched" should read --punched with--.

Line 29, "positions" should read --position--.

Line 56, "by" should read --for--.

Line 61, "way" should read --away--.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. <u>6,912,044</u> B2

No. of add'l. copies @ 30¢ per page



SEP 2 2 2000.

# **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,912,044 B2

DATED

June 28, 2005

INVENTOR(S) :

JUNICHI SEKIYAMA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 1:

Line 55, "let" should read --lets--.

#### COLUMN 3:

Line 64, position" should read --positions--.

### **COLUMN 8:**

Line 9, "10A." should read --100A.--.

#### COLUMN 10:

Line 35, "angle a." should read --angle  $\alpha$ .--

### COLUMN 11:

Line 23, "slid" should read --slide--.

Line 66, "guides" should read --guides to--.

#### COLUMN 13:

Line 64, "a side" should read --a part of the slide guide 302 that is on the upstream side--.

### COLUMN 14:

Line 43, "301 and" should read --301 and 302--.

### COLUMN 15:

Line 21, "rotated" should read --rotated in--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 6,912,044 B2

No. of add'l. copies @ 30¢ per page

SEP 2 2 2005

# **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,912,044 B2

DATED

June 28, 2005

INVENTOR(S) :

JUNICHI SEKIYAMA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 20:

Line 25, 'punched" should read --punched with--.

Line 29, "positions" should read --position--.

Line 56, "by" should read --for--.

Line 61, "way" should read --away--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,912,044 B2

No. of add'l. copies @ 30¢ per page

OFP 2 2 2965